

Test Report No. AJD201301268 Date: MAR.28, 2013 Page 1 of 4

ZHEJIANG XINSHANGCHAO POLYMER CO, LTD

NO.260, YONGNING RD, INDUSTERY AREA OF XIPING, SONGYANG ZHEJIANG CHINA

The following sample(s) was / were submitted and identified on behalf of the client as:

Sample Description: BONDED LEATHER

Test Requested:

The Furniture and Furnishings (Fire) (Safety) Regulations 1988 S.I. No.1324 (amended 1989,1993 and 2010), Schedule 4, Part I, Cigarette test for cover fabrics.

The Furniture and Furnishings (Fire) (Safety) Regulations 1988. S.I. No.1324 (amended 1989, 1993 and 2010), Schedule 5, Part I, Match test for cover fabrics.

As specified in above standard(s) and incorporated with using ignition source 0 and 1 of BS 5852: Part 1:1979.

Test Results: -- See attached sheet --

<u>Conclusion</u>: The tested Sample **Meets** the Requirements of Schedule 4 Part I and Schedule 5 Part I In Statutory Instrument 1988 No.1324 (Amended 1989, 1993 and 2010) the Furniture and Furnishings (Fire) (Safety) Regulations.

Test Period:

Sample Receiving Date

: MAR.21, 2013

Test Performing Date

: MAR.21, 2013 TO MAR.27, 2013

Signed for and on behalf of SGS-CSTC Co., Ltd.

Allen Zou

Technical Supervisor



Test Report

No. AJD201301268

Date: MAR.28, 2013

Page 2 of 4

Test Conducted

The Furniture and Furnishings (Fire) (Safety) Regulations 1988 S.I. No 1324 (amended 1989,1993 and 2010), Schedule 4 Part I and Schedule 5 Part I, Cigarette test and Match test for cover fabric Smouldering Cigarette (ignition source 0) and Match Ignition (ignition source 1) of BS 5852:1979 Part 1

Conditioning

Prior to testing the sample was,

Cleansed using a water-soak procedure at $40\pm1^{\circ}$ C as described in BS 5651:1978 and modified by this Regulations 1988 S.I. No 1324 (amended 1989, 1993 and 2010) Schedule 4 Part I and Schedule 5 Part I.

And then dried and conditioned at least 72 h in indoor ambient conditions and 16 hours in an atmosphere having a temperature of 20±5 ℃ and a relative humidity of 50±20%.

At time of testing: Temperature between 15 °C ~ 30 °C and Relative humidity between 20% ~ 70%

Test results

The following test results only to the ignitability of the combination of materials under the particular condition of test. They are not intended as a means of assessing the full potential fire hazard of the materials or products in use.

(A) Smouldering Cigarette test Criteria		2 nd
Clause 9.2.3 Whether the evidence of progressive smouldering or flaming is observed in the interior and/or cover	NO	NO
Clause 9.2.4 Whether progressive smouldering or flaming of the sample is observed at any time within one hour of placement of the cigarette	NO	NO
Clause 9.2.5 Whether progressive smouldering is observed on final examination when dismantle assembly and examine internally	NO	NO
(B) Butane Flame test Criteria	1 st	2 nd
Clause 9.3.4 Whether the evidence of flaming or progressive smouldering in the interior and/or cover is observed beyond 120s of the removal of the burner tube		NO
Clause 9.4 On final examination whether progressive smouldering is observed when dismantle assembly and examine internally		NO

To be continued....



Test Report

No. AJD201301268

Date: MAR.28, 2013

Page 3 of 4

Test Details

Cigarette Test					
Specimen No.		1 st	2 nd		
Ignition (I) / Did not ignite (DNI) / Ignite but extinguished (IBE) / Surface flash burn (SFB)		DNI	DNI		
Progressive smouldering (PS) or Flaming (F)		NO	NO		
Duration of	Ignition source (min, sec)	19min49s	19min52s		
	Flames (min, sec)	0	0		
	Smoke (min, sec)	19min55s	19min59s		
Finial examination of progressive smouldering (9.4)		NO	NO		
Reason for failure (Ref to failure code)					
Comments & observations					
Overall Result		PASS	PASS		

Match Test					
Specimen No.		1 st	2 nd		
Ignition (I) / Did not ignite (DNI) / Ignite but extinguished (IBE) / Surface flash burn (SFB)		DNI	DNI		
Progressive smouldering (PS) or Flaming (F)		NO	NO		
Duration of	Ignition source (19-21 sec)	20s	20s		
	Flames (min, sec)	0s	0s		
	Smoke (min, sec)	18s	23s		
Finial examination of progressive smouldering (9.4)		NO	NO		
Reason for failure (Ref to failure code)					
Comments & observations					
Overall Result		PASS	PASS		

<u>Statements</u>: The submitted sample was tested in combination with standard worse case scenario non-flame retardant conventional polyurethane foam as specified in the Regulations.

To be continued....

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/terms_and_conditions. htm and,for electronic format documents,subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability indemmines from a finite state of the company of the of the com

s Co. Lill 301#、Sunlight Road, 2 Block, Sunlight Industry Zone, Anji County, Zhejiang Province, China 313300 t (86-572) 5018825 f (86-572) 5018829 www.cn.sgs.com 中国・浙江・安吉县阳光工业园二区阳光大道301号 邮编: 313300 t (86-572) 5018825 f (86-572) 5018829 e sgs.china@sgs.com



Test Report No. AJD201301268 Date: MAR.28, 2013 Page 4 of 4

Photo Appendix:

Details of sample:

Color: Beige

This fabric sample of approximate density of 471g/m².



*** End of Report ***

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/terms_and_conditions. htm and,for electronic format documents,subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability in the limitation of liability in the limitation of standard properties and the standard properties of the Company's findings at the time of its intergraph of the standard within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document of the sone to exonerate parties to a transaction from exercising all their Norths and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Ayxinauthorized alteriation, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

The solution of the content or appearance of the document is unlawful and offenders may be prosecuted to the fullest extent of the law.

8 00、Lill 301#, Sunlight Road, 2 Block, Sunlight Industry Zone, Anji County, Zhejiang Province, China 313300 t (86-572) 5018825 f (86-572) 5018829 www.cn.sgs.com 中国・浙江・安吉县阳光工业园二区阳光大道301号 邮编: 313300 t (86-572) 5018825 f (86-572) 5018829 e sgs.china@sgs.com